


Internal Memorand Oate December 23, 1969 Lottor No. To File From D/541 Subject ALUMINUM PLATING, D/862

an's or shows about a second rate of the set of the second s

I. Layout of area:



- II. Shutdown of the aluminum plating activities
 - A. These activities were shut down on December 18, 1969 by
- III. Since the facility has been shut down, the following modifications have been made to provide additional protection in the area
 - 1. All the chemical processing tanks and miscellaneous equipment at location number one have been removed and the area has been cleaned up.
 - 2. The chemical processing tanks under the hood number two have been modified and rearranged. The solutions not necessary have been disposed of an the area has been cleaned up considerably.
 - 3. The written procedure for aluminum plating is being re-circulated and signed off by individuals working in the area and is being posted in the area.
 - 4. A non-explosion proof duplex receptacle in the glove box number eight has been removed.