

Room 212 & 216


Type of Survey Kad & Cont.

Date 12-26-41

Requested By Routine

Time 1900

Surveyor PM



Clearing of shaded areas recommended

Room 204-207


Type of Survey WATER RD.

Date 12-26-61

Requested by ROUTINE

Time 0100

Surveyor SOMERS



FLOOR OK

SUGGEST CLEANING INDICATED BENCH TOPS

SAMPLE 30 m/h AR

120 cfm BY

2800 fpm

SAMPLES 120 m/h AR

SOUTH ACCESS CORRIDOR


Date: 12-22-61

Time: 11:00

Type of Survey: ADD'L SURV.

Requested by: R

Surveyed by: W.W. & C.M.



Room MC ME AREA


Type of Survey AS L & L CAD

Date 12-23-51

Requested By R

Time 11:20

Surveyor WV & CM



NORTH ACCESS CORRIDOR


Date: 12-23-61


Time: 11:40

Type of Survey: 1108 5-11

Requested by: R

Surveyed by: WW & CM





AREA 602- Basement
 DATE 12-27-51
 TIME 1100

TYPE OF SURVEY Red + Cont
 REQUESTED BY R
 SURVEYOR WW + CM


X CELL

DATE 12-19-61

TYPE OF SURVEY d.B.F

TIME 1515

SURVEYOR JM Rodgers




X CELL

DATE 12-18-61

TYPE OF SURVEY α

TIME 1540

SURVEYOR J M Rodgers




X CELL

DATE Dec 14, '61

TYPE OF SURVEY α

TIME 1500

SURVEYOR JM Rodgers



Room Shift Control Lab.


Type of Survey Contamination & Radiation

Date 12-14-61

Requested By H.P.

Time 1445

Surveyor [Signature]



Recommend changing paper & cleaning floor of East hood

Paper 300 c/m

Hood Floor 3500 c/m

Room RAF Area

Type of Survey Contamination

Date 12-14-61



Requested by H.P.

Time 1445

Surveyor J.P.H.


Stairway to Shift Lab

"A" Line Box Dolly Corridor



Box Transfer Corridor

RAF Corridor



"B" Line Box Dolly Corridor

Gas Cylinder Storage

Recommend mapping shaded area.

RAF

Room Shift Control Lab.

Type of Survey Cont Rad


Date 12-13-61

Requested By HP

Time 0545

Surveyor TC

Floor LRCG



Recommend
Cleaning
1000 m^2

decontaminate
500 m^2

Room 212 & 216

Type of Survey Smear, B & Y


Date 12/9/61

Requested By HP

Time 0945

Surveyor CWI

Suggest Clearing
shaded areas



Room Shift Control Lab.


Type of Survey Rad. + Cont.

Date 12 2 61

Requested By R

Time 0500

Surveyor WJW



340 2/19

Room Shift Control Lab.


Type of Survey RAD + COAT

Date 12-1-61

Requested By R

Time 0400

Surveyor M. SER



Room 204-211


Date 11-27-61

Time 0500

Type of Survey CONT.

Requested by ROUTINE

Surveyor S & TH



Operating Corridor and Sample Corridors

Date 11-27-61

Time 0600


Type of Survey Smear

Requested by HP

Surveyor FJK

Recommend mopping area under pipe, and stopping leak.

EAST SAMPLE CORRIDOR



Water leaking from overhead pipe 1,000 c/m

Room 212 & 216


Date 11-27-61


Time 1900

Type of Survey Rad. & Cont.

Requested By Routine

Surveyor PM & CWJ





AREA 602- Basement
 DATE 11-25-61
 TIME 1000

TYPE OF SURVEY RAD. & CORR.
 REQUESTED BY R
 SURVEYOR W.W. & CA

NORTH ACCESS CORRIDOR


Date: 11-25-61

Time: 1000

Type of Survey: Rad + Cont.

Requested by: R

Surveyed by: WUHCM



Room WG-WH AREA


Type of Survey RAD + CANT.

Date 11-25-61

Requested By R

Time 1600

Surveyor WU + CM



SOUTH ACCESS CORRIDOR


Date: 11-25-61

Time: 1000

Type of Survey: RAD + CONT

Requested by: R

Surveyed by: W W + C M



Room 212 & 216


Type of Survey Count + Rad

Date 11-20-61

Requested By Routine

Time 0200

Surveyor PM + CWT



Recommend
cleaning of
shaded
areas.

Room 204-207

Type of Survey ROUT. + RAD.


Date 11-19-61

Requested by ROUTINE

Time 0930

Surveyor S + T.H.

FLOOR ^(OK)
SUGGEST CLEANING
INDICATED
BENCH TOPS



Room 212 & 216


Type of Survey _____

Date 11-12-61

Requested By Routine

Time 1015

Surveyor Maeser & Landolt



Recommend cleaning of shaded areas

Room 212 & 216


Type of Survey R & C

Date 11-2-41

Requested By Rutledge


Time 1730

Surveyor Moser



Area
ok.

20



AREA 602 - Basement

DATE 10-28-61

TIME 1100

TYPE OF SURVEY Rad Y - Cont

REQUESTED BY R

SURVEYOR Moser

Room 212 & 216


Type of Survey RFC

Date 10-23-61

Requested By Rortine

Time 0200

Surveyor Maesen



Room 212 & 216


Type of Survey R+C

Date 10-9-61

Requested By Partis


Time 1930

Surveyor Maer



Please change paper on this mat.

Please remove paper from this mat.



AREA 602- Basement

DATE 9-29-61

TIME 1400

TYPE OF SURVEY Rad + Cont

REQUESTED BY R

SURVEYOR Moser

Room WG WE AREA


Type of Survey Rad + COND

Date 9-29-61

Requested By R


Time 1400

Surveyor MOSEK



Room Basement
Date 9-29-66
Time 1400

Type of Survey Rd & COND
Requested By R
Surveyor MOSER



Room 212 & 216


Type of Survey R/C

Date 9-25-61

Requested By Practice

Time 0030

Surveyor Maass



Area Nitrogen Plant


Date 8-24-64 Time 1900

Type of Survey Red + comb.

Requested By R

Surveyor MOSEN

2 RCG B, 8, 2



Area 604 Sample Corridor


Date 8-24-61 Time 1900

Type of Survey Rad + Cont'

Requested By R

Surveyor Moser

2 PCB B, V, 2




Area 604 Service Corridor

Date 8-24-61 Time 1900

Requested By R

Type Of Survey Rad + Comp.

Surveyor MOSER



L R C G B, Y, L

O DRAIN

O DRAIN

Area 604 Access Corridor


Type of Survey Rad & Cont.

Date 8-24-41

Requested by R

Time 1900

Surveyor MOSER



200 Halls & Rooms

Date 8-20-61

Time 1000


Surveyor RJ

Mens Locker Room

60 c/m
206

Womens
Locker
Room

Shower



224

218

214

226

220

216

212

208

204

North Sink

227

20 c/m

223

211

207

229

225

221

217

217

215

213

209

Closest



Elevator

202

200

201

203



Rooms Decontamination and Multi Curie


Date 8-1-61

Time 1930

Type of Survey Rad & Cont.

Requested by Rout.

Surveyor Maesen



RAF Main Corridor

Bench
Sink
Shap Cover area
Hoods

Floor
< RCG
B, Y, alpha

Closed Cell →

Hot Boxes
5 R/m

Hot Plate
400 m/m

Resp & Sack
300 m/m

Multi Curie Cell Room

Analytical Boxes

Remote Hood

Barrel
400 m/m

Tank

Steam Cab.

Electro. Decont.

Sink

Decontamination Room

Shoe Decont.

Hood

ribbon


↑ N

Date 7-26-61

Surveyor Moser

606 Bldg

Time 1930




PCG B, 8, 2

c/m

618 Bldg.

Now
7-26-81
N



Lunch room B, S, 2

314

Survey *Moser*
Date *2-26-61*
Time *19.30*.....

304

V.E.S.

321

319

317

315

313

311

Men

Women

Chem
Storage

Elevator

RPCG 32B, 8, 2

312

Women
310

Men
308

306

Closet

309

307

302

300

301

303

Room 212 & 216


Date 7-15-61

Time 1830

Type of Survey Rad-Cont.

Requested By C.V.

Surveyor RJ



Hood Ledge
200 c/m d

Replace ment of - in asking tape
on Hood ledge recommended -

Room 212 & 216

Date 7-5-61


Time 0400

Type of Survey Rad. Cont.

Requested By _____

Surveyor RT

Cleaning recommended on exterior of glove box especially the top where dust has collected. Also the removal of contaminated masking tape from the hood ledge.



Room 204-208


Date 7-2-61

Time 1100

Type of Survey CONT. & RAD.

Requested by ROUTINE

Surveyor SOMERS



SUGGEST
CLEANING
SHADED AREAS